

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

2005210-05F4550

1/36

FIG.1






FIG.2



202-293-7060


FIG.3



202510-05F4660

4/36


FIG.4



202-293-7060

5/36


FIG.5



09937130.01900

6/36

FIG.6



0937130.01290

7/36

FIG.7






FIG.8



2025-07-08 09:00:00


FIG.9



200210-0814660


10/36

FIG.10



206210-06F4E660


FIG.11



206210-05F C6660

12/36

FIG.12




0937130.012902



13/36

FIG.13



200210-05T25560

FIG.14A






FIG.14B



15/36



FIG.15



0037130-01280

FIG.16A


FIG.16B



2009-09-13 09:00:00

17/36


FIG.17



09/937130-012902

18/36

FIG.18



2002-01-26

19/36

FIG.19A





FIG.19B



20/36

FIG.20D




FIG.20C




FIG.20B





FIG.20A



2062FD-DEFCEBDD

FIG.21A






FIG.21B



0937130-012902

22/36

FIG.22



23/36

FIG.23




FIG.24




FIG.25A





FIG.25B



09937130.012903

206210-06145660

25/36

FIG.26A




FIG.26B




FIG.26C




FIG.26D





FIG.27



27/36

FIG.28A




FIG.28B






FIG.28C




0937130.012902

FIG.29



09/937,130 - 012902

FIG.30



200210-01F2E660

FIG.31A




FIG.31B




FIG.32B




FIG.32A




FIG.33B





FIG.33A



2002FO-DET/2E560

33/36

FIG.34A





FIG.34B



09937130-012902

FIG.35A




FIG.35B




FIG.36A





FIG.36B



09937130-012902

35/36

FIG.37A





FIG.37B



200210-012902

